

CASE HISTORY: BENTOFIX GOLF HAZARD.



Bentofix Pond in play on hole number 2 & 3 at River Bend Golf Course. June 2005.



Geosynthetic Clay Liner, Bentofix, being installed by Terrafix Environmental Inc. during the summer of 2001.

BACKGROUND: The Thames River Watershed provided nothing but sand. However, golfers need more than bunkers. A Geosynthetic Clay Liner, Bentofix CNSL, provided a liner with a permeability equivalent to other membranes on the market (5×10^{-13} cm/sec). Golfers would never know during their play of Hole 2 and 3 on the River Bend Golf Course that a Bentofix Hazard is in play on both holes. Bentofix Technologies Inc. is not responsible for lost or stolen golf balls. Visit www.riverbendgolf.com for more information on this golf course jewel in the Forest City of London, Ontario.

Since the late 1980s, GCLs have been specified and used by design engineers, agencies and owners as an alternative to soil barriers in various applications. For further information on GCLs for your golf course pond and/or other lining applications contact your local representative. In Western Canada contact AGES at 403.204.3322, in Atlantic Canada contact Arrow Construction Products at 506.452.8178 Fredericton or 902.468.1551 Halifax, or contact Terrafix direct at 416.674.0363. www.terrafixgeo.com or www.bentofix.com